

03500.017706.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TOSHIKO MORII et al.) Examiner: F. Polyzos
Appl. No.: 10/705,860) Group Art Unit: 2878
Filed: November 13, 2003)
For: IMAGE PICKUP APPARATUS,)
RADIATION IMAGE PICKUP)
APPARATUS AND RADIATION)
IMAGE PICKUP SYSTEM)
U.S. Patent No.: 6,989,540 B2)
Issued: January 24, 2006) September 28, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

*Certificate
OCT 03 2006
of Correction*

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee
for such Certificate of Correction.

10/02/2006 SDENB0B1 00000353 6989540

01 FC:1811

100.00 OP

Void date: 10/02/2006 SDENB0B1 00000353 6989540
10/02/2006 SDENB0B1 00000353 6989540
01 FC:1811 100.00 OP
10/02/2006 SDENB0B1 00000353 6989540
01 FC:1811 100.00 OP

OCT - 3 2006

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


John D. Magluyan
Attorney for Patentees
Registration No.: 56,867

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 119208v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,989,540 B2

DATED : January 24, 2006

INVENTOR(S) : Morii et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 48, "detect" should read -- defect --.

COLUMN 3:

Line 25, "from" should be deleted.

COLUMN 9:

Line 6, "ohmic" should read -- first ohmic --.

COLUMN 12:

Line 20, "wiring. 201," should read -- wiring 201, --.

COLUMN 13:

Line 19, "layer" should read -- layer structure --.

COLUMN 15:

Line 3, "complicated therefore," should read -- complicated. Therefore, --.

COLUMN 16:

Line 55, "TFT, After" should read -- TFT. After --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,989,540 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
119206 (Form#30)

→

OCT - 3 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : 6,989,540 B2

DATED : January 24, 2006

INVENTOR(S) : Morii et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 44, "another," should read -- other, --.

COLUMN 19:

Line 63, "X-ray On" should read -- X-ray. On --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,989,540 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
119206 (Form#30)

OCT - 3 2006 →

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,989,540 B2
DATED : January 24, 2006
INVENTOR(S) : Morii et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 48, "detect" should read -- defect --.

COLUMN 3:

Line 25, "from" should be deleted.

COLUMN 9:

Line 6, "ohmic" should read -- first ohmic --.

COLUMN 12:

Line 20, "wiring. 201," should read -- wiring 201, --.

COLUMN 13:

Line 19, "layer" should read -- layer structure --.

COLUMN 15:

Line 3, "complicated therefore," should read -- complicated. Therefore, --.

COLUMN 16:

Line 55, "TFT, After" should read -- TFT. After --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,989,540 B2No. of add'l. copies
@ 30¢ per page

OCT - 3 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,989,540 B2

DATED : January 24, 2006

INVENTOR(S) : Morii et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 44, "another," should read -- other, --.

COLUMN 19:

Line 63, "X-ray On" should read -- X-ray. On --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,989,540 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
119206 (Form#30)

OCT - 3 2006

→